

**Observer-i Gas Leak Detector – ATO Order Form**

**Gasonic Observer-i**

OBSERVERI-1000	4-20mA source current, dual Modbus, Alarm de-energized, M20 screw terminal, (EA01)
OBSERVERI-1001	4-20mA source current, dual Modbus, Alarm de-energized, M20 screw terminal, Classic mode
OBSERVERI-1002	3.5mA HART, source current, single Modbus, Alarm de-energized, M20 screw terminal, (EA01)
OBSERVERI-1003	3.5mA HART, source current, single Modbus, Alarm de-energized, M20 screw terminal, Classic mode
OBSERVERI-1004	1.25mA HART, source current, single Modbus, Alarm de-energized, M20 screw terminal, (EA01)
OBSERVERI-1005	1.25mA HART, source current, single Modbus, Alarm de-energized, M20 screw terminal, Classic mode
OBSERVERI-1006	4-20mA source current, dual Modbus, Alarm de-energized, 3/4" NPT screw terminal, (EA01)
OBSERVERI-1007	4-20mA source current, dual Modbus, Alarm de-energized, 3/4" NPT screw terminal, Classic mode
OBSERVERI-1008	3.5mA HART, source current, single Modbus, Alarm de-energized, 3/4" NPT screw terminal, (EA01)
OBSERVERI-1009	3.5mA HART, source current, single Modbus, Alarm de-energized, 3/4" NPT screw terminal, Classic Mode
OBSERVERI-1010	1.25mA HART, source current, single Modbus, De-energized, 3/4" NPT screw terminal, (EA01)
OBSERVERI-1011	1.25mA HART, source current, single Modbus, De-energized, 3/4" NPT screw terminal, Classic mode

**NOTE:** Approvals for all units are CSA/FM – ATEX/IECEX  
Microphone Assembly for all units is NGMM  
Consult factory for other configurations



**Accessories**

**Gasonic Observer-i**

805773-1	Microphone
805554-3	Sound Assembly
80601-1	Assembly Mounting Bracket
805708-1	Windscreen Support Assembly
80602-1	Torque Wrench for Observer
80499-1	Magnet Stick for Display
80333-1	Windscreen
80610-1	Tag Plate Extra
80612-1	Sun Shade
914-169	Adapter M20 to 3/4 NPT Brass EExd

**Gasonic 1701**

80575-1	Battery Pack Assembly
80570-1	Battery Charger 1701
80538-1	Calibration Process
80510-1	Portable Test & Calibration Unit
80499-1	Magnet Stick for Display